

Keeley Construction Top 10 Good Catches for the Week of 2/13/23

Rank	Submitted By	Group	GC Type	ObservationMade	Deficiencies	Recommendation Eliminate Occurance
1	Joe Philipp	Building	Vehicular/Equipment	Operator no seat belt (RTLb)	No seat belt	Always wear seat belt
	Kevin Grzesiowski			Not wearing seatbelt in skid steer (RTLb)	Both operators were not wearing their seatbelts while operating their skid steers	Discuss during JSA and vehicle inspection
2	Darrin Justus	Civil	Caught Between/Struck By	Worker exposed themselves to a struck by/caught between situation	Worker chose a path that took them towards an approaching excavator bucket.	Remind workers, especially the younger ones, to stay "in tune" with task & make smart decisions.
3	Silver Mendez	Paving	Electric/Tools;JSA / Planning;PPE;Slips / Trips / Housekeeping;Strains and Sprains;Other	Extension cord laying on water	Electricity & water don't mix	Made sure connecting points are not making contact with water
4	Jason Myatt	Industrial	Flammables / Fire Protection	I received a call today for a emergency repair to a trash compactor. We called our millwright team and was able to get them scheduled for a Saturday morning repair. So once I knew we where going to be completing the work I went out to St. Charles campus to get my eyes on the project. Once I arrived i noticed that the compactor that we needed to weld on was for a hazardous material container.	Boeing did not do a proper investigation into what all of the issues where.	Stay vigilant even with Customer instructions/direction
5	Kevin Bell	Paving	Other	Slick surface	Pavement slick	We noticed on our morning walk through
6	Mark Musser	Civil	Work Zone Traffic Control / Jobsite Access	Goal post style warning sign needed to be place under a power line at the rear gate	Pole was recently installed and gate hadn't been in use	Always be on the lookout for new hazards
7	Matt Sitze	Civil	Rigging	Shackle was wore out and wouldn't close all the way	When pin was screwed down it wouldn't come all the way to the end	
8	Nicholas House	Civil	Rigging	Under inspection prior to use, inner red cord was showing on 16' strap	Rigging frayed, red is dead, inner red cord is showing	Wear and tear set,
9	Austin Smith	Industrial	Fall Protection / Ladders / Scaffolds	Windows fully opened presented falling hazard	2 foot wide by 4 foot tall opening at 12 feet from ground level with no mid-rail or guarding at handrail height	Need kind term a mid rail accords window for owner use. Construction use limiting the ability to open the window and identifying hazard and reason for limit to all on site.
10	Evan Kamp	Building	Fall Protection / Ladders / Scaffolds	Worker using ladder improperly.	Field crew member leaning an "A" framed ladder, not designed to be leaned.	
	Chris Gross			Ladder usage	Using standard ladder in leaning position	Use the right tool for the job
				Using a bucket as a ladder	Wrong tool used	Use the correct tool